



### INSTRUCTIONS

FOR THE USE OF

## A. W. FABER'S

IMPROVED

## CALCULATING RULE.

BY

CHARLES N. PICKWORTH, Wh. Sc.,

Author of "The Slide Rule," etc.

MANUFACTORY ESTABLISHED 1761.

Prize Medals from all Important

International and Industrial Exhibitions.

#### MANUFACTORIES IN

GERMANY, FRANCE, AND UNITED STATES.

HOUSES IN

LONDON, PARIS, BERLIN, AND NEWARK, N.J., U.S.A.

### A. W. FABER,

41-47, DICKERSON STREET AND 64-88, HECKER STREET,

Newark (N.J.), U.S.A.

# CONTENTS.

| Introduction              | 20200    |               |          |        |         |   | PAG        |
|---------------------------|----------|---------------|----------|--------|---------|---|------------|
| Construction of the Cale  | culating | Rule          |          | •••    | •••     | •••                                     | - 5        |
| The Scales                |          |               |          | •••    | •••     | •••                                     | 5          |
| Dropoution                |          |               | •••      | •••    | •••     | •••                                     | б          |
| Multiplication            |          | •••           | •••      | •••    | •••     | •••                                     | · II       |
| Division                  |          |               | •••      | •••    | •••     | •••                                     | 14         |
| Combined Multiplication   | and D    | ···<br>i-si-t | •••      | •••    | •••     | •••                                     | 15         |
| The Inverted Slide        |          |               |          | •••    | • • •   | •••                                     | 16         |
|                           | •••      | •••           | • • •    | • • •  | •••     | •••                                     | 17         |
| Squares and Square Ro     |          | •••           | •••      | • • •  | •••     | •••                                     | 18         |
| Cubes and Cube Roots      |          | •••           | • • •    |        | •••     | •••                                     | 19         |
| Fourth Powers and Roo     | ts       | •••           | • • •    | •••    | •••     | • • •                                   | 22         |
|                           |          |               |          |        |         |   |            |
| PRACTICAL ILLU            | STRATI   | ONS           | F THE    | USE    | OF T    | HE                                      |            |
| C                         | ALCULA   | TING          | RULE.    |        |         |   |            |
| Mensuration, etc          | •••      |               |          |        |         |   | 23         |
| Screw Cutting             |          |               |          |        |         |   | 25         |
| Gearing, etc              |          |               |          | •••    |         |   | <b>2</b> 6 |
| Delivery from Pumps       |          |               |          |        |         |   | 29         |
| Power of Steam Engines    |          |               |          |        |         | • | 29         |
|                           |          |               |          |        |         | •••                                     | 29         |
| THE TRIGONOM              | ETDICA   | т Ав          | DI 10 AT | TONG   | ori mur | _                                       |            |
|                           | ALCULA   |               |          | IONS ( | OF TH   | E                                       |            |
| T1 C 1 ( C)               |          | IING          | RULE.    |        |         |   |            |
|                           |          | •••           |          | • • •  | •••     | •••                                     | 31         |
|                           | •••      | • • •         | •••      | •••    | •••     |   | 33         |
| The Scale of Logarithms   |          |               | •••      | •••    | •••     | •••                                     | 34         |
|                           |          |               |          |        |         |   |            |
| IMPROVED FORM OF          | A. W.    | FABI          | ER'S C   | ALCUL  | ATING   | RULE.                                   |            |
| Rule with Digit Registeri | ng Curs  | sor           | •••      |        |         |   | 36         |
| Number of Digits in a P.  | roduct . |               |          |        |         |   | 37         |
| Number of Digits in a Qu  |          |               |          |        |         |   | 38         |
| Combined Multiplication   |          |               |          |        |         |   | 39         |
| Circumference and Area of |          |               |          | •••    |         |   | 44         |
|                           |          |               |          |        |         |   |            |

| A. W.      | Faber's   | CALC  | CULATI  | ٧G  | RULE  | FOR   | ELECTI | RICAL | AND  |
|------------|-----------|-------|---------|-----|-------|-------|--------|-------|------|
|            |           | ME    | CHANIC  | AL  | ENGIN | EERS. |        |       |      |
|            |           |       |         |     |       |       |        |       | PAGE |
| Log Log    | Scales    | •••   |         |     |       |       | •      | •••   | 46   |
| Involution | (Raising  | to F  | Powers) |     |       |       |        |       | 47   |
| Evolution  | (Extract  | ing I | Roots)  |     |       |       |        |       | 47   |
| Efficiency | of Dyna   | mos   | •••     | ••• |       |       | •••    |       | . 48 |
| Efficiency | of Moto   | rs    |         |     |       |       |        |       | 49   |
| Scale of 1 | Loss of I | oten  | tial    |     |       |       |        | •••   | 49   |
|            |           |       |         |     |       |       |        |       |      |
| INS        | TRUCTION  | NS FC | R THE   | " F | ICKWO | RTH " | SLIDE  | RULE  |      |

52

To find the Cube of a Number ...

Cube Roots