INSTRUCTIONS

FOR THE USE OF

A. W. FABER'S

IMPROVED

CALCULATING RULE.

BY

CHARLES N. PICKWORTH, Wh. Sc.,

Author of " The Slide Rule," etc.

MANUFACTORY ESTABLISHED 1761.

Prize Medals from all Important

International and Industrial Exhibitions.

MANUFACTORIES IN

GERMANY, FRANCE, AND UNITED STATES.

HOUSES IN

LONDON, PARIS, BERLIN, AND NEWARK, N.J., U.S.A.

A. W. FABER,

149, QUEEN VICTORIA STREET,

London, E.C.



CONTENTS.

					DAG
Introduction					PAG.
Construction of the Calculatin	g Rule			•••	.5
The Scales					6
Proportion					11
Multiplication					. 14
Division				150) R
Combined Multiplication and				•••	15 16
The Inverted Slide				•••	- 46'4
Squares and Course Day	337,700.00		•••	•••	17
Cubes and Cube Roots			•••	•••	18
Fourth Powers and Roots			• • •	•••	19
10003	•••	• •••		•••	22
Dr. Contact Transcon					*
PRACTICAL ILLUSTRA			E OF	THE	
	LATING R	ULE.			10
Mensuration, etc			• • •		23
Screw Cutting			•••		25
Gearing, etc			•••	•••	26
					29
Power of Steam Engines					29
THE TRIGONOMETRIC	CAL APPL	ICATIONS	OF TH	41	
	LATING R		01 11		,
TL C 1 CC					
The Scale of Tangents		•••	•••	•••	31
The Scale of Logarithms			•••	•••	33
The Scale of Logarithms		•••	•••	•••	34
	E .	87			
IMPROVED FORM OF A. V	V. FABER'	S CALCU	LATING	RUL	E.
Rule with Digit Registering Cu	ırsor			• • •	36
Number of Digits in a Product					3 <i>7</i>
Number of Digits in a Quotien					38
Combined Multiplication and I				•••	40
Circumference and Area of a C					3 9

A. W. Faber's Calculating Rule for Electrical and Mechanical Engineers.

	1			PAGE
Log Log Scales			• • •	46
Involution (Raising to Powers)				47
Evolution (Extracting Roots)				47
Efficiency of Dynamos			•••	48
Efficiency of Motors			•••	49
Scale of Loss of Potential			•••	49
THE "PICKWORTH"	SLIDE	RULE.		10
To find the Cube of a Number				52
Cube Roots	.,, .			53