



INSTRUCTIONS

FOR THE USE OF

A. W. FABER'S

CALCULATING RULE.

CHARLES N. PICKWORTH, Wh. Sc.,

Author of the "The Slide Rule," etc.

MANUFACTORY ESTABLISHED 1761.

Gold and first=Class Prize Medals.

MANUFACTORIES AT
STEIN, GEROLDSGRÜN, AND NOISY-LE-SEC.
HOUSES IN

LONDON, PARIS, BERLIN, AND NEW YORK.

A. W. FABER,

78, READE STREET,

New York.

CONTENTS.

							PAGE
Introduction			•••		•••		5
Construction of the Calcula	ting F	Rule	•••		***		5
The Scales		• • •		•••		• • • •	6
Proportion	•••		•••			•••	ΙI
Multiplication		•••	•••			•••	14
Division				•••	• • • • •		15
Combined Multiplication an	d Div	ision	•••	• • •			16
The Inverted Slide			•				17
Squares and Square Roots			• • •	•••		•••	18
Cubes and Cube Roots	•••	•••	* ***	•••		• • •	19
Fourth Powers and Roots					•••		22
Practical Illustr				OF T	HE		
CALCUI	ATING	KULE	:-				
Mensuration, etc	•••		•••	•••	•••	•••	23
Screw Cutting	•••	•••	•••	•••	••••	•••	25
Gearing, etc	• • • •	•••	•••	•••	•••	• • • •	26
Delivery from Pumps		•••	•••	• • • •	•••	•••	29
Power of Steam Engines	• • • •	•••	•••	•••	•••	•••	29
		۸			_		8.9
THE TRIGONOMETE				OF TH	E		
Calcul	ATING	NULE	·				
The Scale of Sines	•••		• • •	• • •	•••	•••	31
The Scale of Tangents	•••	•••	•••	•••	•••	•••	33
The Scale of Logarithms	•••	•••	•••	•••			34